

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2025

Submitted Date:

02/26/2025

Document Number:

707603699**FIELD INSPECTION FORM**Loc ID 413457 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412513	WELL	PA	04/21/2020	OW	123-30597	NORTH PLATTE 31-34	PA

**General Comment:**This is a **PLUGGED & ABANDONED WELL** inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location IDs  
(413974).

(Well(s): 2: Temporarily Abandoned | TA).

Centralized Battery Formerly served 1 Location IDs  
(413457).

(Well(s): 2: Plugged &amp; Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID  
(Pending).

Reference (Associated Well(s), Battery Inspections):

A.) Field Inspection Report doc. #707603695 and/or Location ID #413974  
for TA Well(s) info.B.) Field Inspection Report doc. #707603697 and/or Location ID #413974  
for TA Well(s) info.C.) Field Inspection Report doc. #707603699 and/or Location ID #413457  
for PA Well(s) info.D.) Field Inspection Report doc. #707603701 and/or Location ID #413457  
for PA Well(s) info.E.) Field Inspection Report doc. #707603703 and/or Location ID #413974  
for Battery / Facility, Equipment info.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 0		corrective date
Comment:	Assigned to Loc ID: 413974.		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	Assigned to Loc ID: 413974.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Assigned to Loc ID: 413974.				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance	
Comment:								
Corrective Action:							Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS	
CRUDE OIL		0					,	
Comment:	Assigned to Loc ID: 413974.							
Corrective Action:							Date:	

**Paint**

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 412513 Type: WELL API Number: 123-30597 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On MON 02/24/2025 at approximately 14:35 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte/32-34 Location ID: 413457 Well Name(s) &amp; API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Battery: Inactive   Shut-down.</p> <p><b>WELL STATUS COMMENT:</b> Plugged &amp; Abandoned   PA. Form 6-SRA on file. Plugging, cut/cap date: 04/21/2020. Approved. Plugged &amp; Abandoned   PA well GPS coordinates: 40.361390 / -104.420110</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	02/26/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603700	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936494">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936494</a>