

Comment: No spill prevention was observed at lube/oil tank at pump jack.

Corrective Action: Comply with rule 1002f. Install spill prevention at lube/oil tank.



Comment: Unused oil and gas equipment observed at pump jack.

Corrective Action: Comply with rule 606. removed unused oil and gas equipment.



Comment: Erosion observed on the western edge of the pad.

Corrective Action: Comply with rule 1002f. Install or repair required BMPs.



