

**Inspection Photos**  
**Location: Frazee 2-6**  
**Location ID: 324831**  
**API # 05-061-06365**



**Photo 1 –Well placard**


**Photo 2 – Wellhead and Pump Jack**



**Inspection Photos**  
**Location: Frazee 2-6**  
**Location ID: 324831**  
**API # 05-061-06365**



**Photo 3 – Wellhead covered in oily sludge**



**Photo 4 – Stained oils**

**Inspection Photos**  
**Location: Frazee 2-6**  
**Location ID: 324831**  
**API # 05-061-06365**



**Photo 5 –Tank Battery**



**Photo 6 – Containment reconstructed**



**Inspection Photos**  
**Location: Frazee 2-6**  
**Location ID: 324831**  
**API # 05-061-06365**



**Photo 7 – Impacted soils in tank containment, Spill Id 486875, Impacted soils observed at tank base**



**Photo 8 – Impacted soils in tank containment, Spill Id 486875**



**Inspection Photos**  
**Location: Frazee 2-6**  
**Location ID: 324831**  
**API # 05-061-06365**



**Photo 9 – Impacted soils observed on north side of tank, Spill Id 486875**



**Photo 10 – Tank battery and equipment on north side of road**



**Inspection Photos**  
**Location: Frazee 2-6**  
**Location ID: 324831**  
**API # 05-061-06365**



**Photo 11 –Tank had been removed**



**Photo 12 – Historical Photo 11/26/2024**



**Inspection Photos**  
**Location: Frazee 2-6**  
**Location ID: 324831**  
**API # 05-061-06365**



**Photo 13 –Historical Tank 11/26/2024**



**Photo 14 – Tank has been removed**