

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2025

Submitted Date:

02/27/2025

Document Number:

710500432**FIELD INSPECTION FORM**Loc ID 314207 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 61250

Name of Operator: MULL DRILLING COMPANY INC

Address: 1700 N WATERFRONT PKWY B#1200

City: WICHITA State: KS Zip: 67206-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Welsh, Brian		brian.welsh@state.co.us	
Damme, Dustin	316-895-1596	ddamme@mulldrilling.com	
Mull, Jennifer	(316) 264-6366	jmull@mulldrilling.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228033	WELL	PA	06/29/2022	OW	099-06360	SANTA FE RANCH 24-14	EI
314207	LOCATION	CL			-	SANTA FE RANCH- 621S46W 24SESW	EI

General Comment:[This is an Environmental Inspection for the Santa Fe Ranch 24-14, API 05-099-06360, Rem # 23974](#)

Location

Lease Road:			
Type	Access		
comment:	Lease road through pasture.		
Corrective Action	L	Date:	

Overall Good: ☐

Emergency Contact Number:

Comment: Well placard at fence line where lease road and county road intersect

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	There is an open excavation adjacent to County Road SS, at the time of inspection the temporary fence was in disrepair. Excavation does have an ingress egress ramp. However, sidewalls of excavation are steep and create a hazard to health and safety.		
Corrective Action:	Per Rule 913.b.(5).B.i. Operators will fence or cover open excavations to prevent access when sites are not attended. Operator shall repair fencing	Date:	03/07/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	228033	Type:	WELL	API Number:	099-06360	Status:	PA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	314207	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental		
Spill/Remediation:		
Comment:	Remediation Project # 23974 is ongoing. Operator shall continue quarterly reporting until the site meets Table 915-1 standards.	
Corrective Action:		Date: _____
Emission Control Burner (ECB): _____		
Comment:		
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500433	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6937428