

Inspection Photos

02/24/2025

Operator: SCOUT ENERGY MANAGEMENT LLC
- 10779

Location ID: 315585

Inspection Doc: 718100266

Rio Blanco County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 315585



Photo 1: Photos 1-2 taken from the location entrance on the northeast end of the working pad surface. Photos provide an overview of the Location from south, southwest, west to northwest. Photos also examples showing vehicle tracking and sediment transport control measures are no longer in proper functioning condition, resulting in rutting, degradation and sediment transport.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 315585



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 315585



Photo 3: Photos taken from the access road, facing northeast. Photos examples showing vehicle tracking and sediment transport control measures are no longer in proper functioning condition, resulting in rutting, degradation and sediment transport.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 315585



Photo 4: Photos examples of the interim areas of the Location. Vegetation throughout the interim areas are predominantly weedy annual species such as Annual Wheatgrass and Cheatgrass, however these species are also prevalent throughout the adjacent reference areas. See Photo 5.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 315585



Photo 5: Photo taken from the adjacent reference areas for comparison.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 315585



Photo 6: Photos show cap missing from the secondary containment BMPs. Fluids also observed within containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 315585



Photo 7: Photo example showing halogeton observed established along the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources