

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2025

Submitted Date:

02/27/2025

Document Number:

707603707

FIELD INSPECTION FORM

Loc ID 423412 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481564	TANK BATTERY	AC	02/07/2022		-	70 Ranch BB 21-67HN Tank Battery	AO

General Comment:

This is a TANK BATTERY inspection.
Well(s): 3: Producing | PR.
Battery: Active.

Centralized Battery serves 1 Location ID (423412).
(Well(s): 3: Producing | PR).

Centralized Battery serves 1 Tank Battery Facility ID (481564).

Reference (Associated Well(s), Battery / Facility Inspections):
A.) Field Inspection Report doc. #707603705 and/or Location ID #423412 for PR Well(s) info.
B.) Field Inspection Report doc. #707603707 and/or Facility ID #481564 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Battery site: Methanol, Nitrogen. (Placards).		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Iron pipe.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Iron pipe. Surrounded by earth berms.		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Emission Control Device	# 3		
Comment:	Facility vapor line combustor(s). Controls Facility vapors. Pilots: ON.		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 8		
Comment:	Battery site: 1: Insrument Air tank(s), Nitrogen. 1: Methanol pump(s), tank(s) w/ drip containment. 2: Solar power bank. 4: ECD scrubber(s).		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	2: Gas Sales, Master; (Phillips 66). Calibration card(s) indicates calibration <= 1 year. Last calibration: 02/06/2025.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Location ID (423412). (Well(s): 3: Producing PR). Centralized Battery serves 1 Tank Battery Facility ID (481564).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Shares berms w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	9	300 BBLs	STEEL AST		40.384040,-104.449980
Comment: Equalizer line(s) connect crude oil tank(s).					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Shares berms w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:

Wells Served By Facilities Above		AirsID	
API Number		API Number	AirsID
123-33577			
123-33576			
123-33579			

Venting:	
Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:	
Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 481564 Type: TANK API Number: - Status: AC Insp. Status: AO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 02/27/2025 at approximately 13:51 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Facility Name: 70 Ranch BB 21-67HN Tank Battery/ Facility ID: 481564 Location Name: 70 RANCH BB/21-67HN Location ID: 423412 Well Name(s): See photo(s) #8 attached to this report. API: See "Wells Served By Facilities Above" sec on pg. 4 and/or photo(s) #8 attached to this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 3: Producing PR. Battery: Active.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	02/27/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603708	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6938323