

Inspection Photos
Location: Frontera Unit Gas Plant
Location ID: 480729, Spill ID 489242
API #



Photo 1 –Placard

Photo 2 – Gas Plant

Inspection Photos
Location: Frontera Unit Gas Plant
Location ID: 480729, Spill ID 489242
API #



Photo 3 – Spill Remediation area

Photo 4 – Gas Plant

Inspection Photos
Location: Frontera Unit Gas Plant
Location ID: 480729, Spill ID 489242
API #



Photo 5 –Equipment



Photo 6 – Contaminated soils stored on liner

Inspection Photos
Location: Frontera Unit Gas Plant
Location ID: 480729, Spill ID 489242
API #



Photo 7 –Contaminated soils stored on liner



Photo 8 – Tank in containment

Inspection Photos
Location: Frontera Unit Gas Plant
Location ID: 480729, Spill ID 489242
API #



Photo 9 –Spill Remediation area



Photo 10 – Spill Remediation area

Inspection Photos
Location: Frontera Unit Gas Plant
Location ID: 480729, Spill ID 489242
API #



Photo 11 – Tanks with stained soils no secondary containment



Photo 12 – Spill Remediation