

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2025

Submitted Date:

02/27/2025

Document Number:

710500438

FIELD INSPECTION FORM

Loc ID 480729 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	COGC
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	COGC
MacLaren, Joe		joe.maclaren@state.co.us	
Longworth, Mike		mike.longworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480720	GAS PROCESSING PLANT	AC	08/31/2021		-	Frontera Unit Gas Plant	EI
480729	LOCATION	AC			-	Frontera Unit Press Maint Facility	EI
489242	SPILL OR RELEASE	AC	02/07/2025		-	Frontera Gas Processing Plant	EI

General Comment:

This is an Environmental Inspection for the Frontera Unit Gas Plant, Facility ID 480720, Spill ID 489242

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 480720 Type: GAS API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 480729 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 489242 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment	Impacted soils are stored onsite on a liner with earthen berms surrounding spoil pile. Impacted soils shall be stored, managed and disposed in accordance with Rule 905.			
Corrective Action				Date:

Spill/Remediation:

Comment:	Spill Investigation for Spill ID 489242 is ongoing. At the time of inspection, impacted soils were being excavated and soil samples were being collected. Impacted materials were stored on location within a containment on a plastic liner. COA in Form 19 Document # 404083094 identified a 10-day supplemental Form 19 is due in 10-days to provide additional spill details that were not reported in the initial spill report. The Form 19 Supplemental was due 10-days from the date of report, 2/5/2025, and due on 2/15/2025. Per Rule 912.b Supplemental Form 19s are due 10-days from date of discovery. Due to the CA due date in Field Inspection # 701104134 Operator filed the Initial Spill report on 2/5/2025. The due date for the supplemental Form 19 was 2/15/2025 and is 13 days late.	
Corrective Action:	Per Rule 912.b.(4), the Operator shall make a supplemental report on Form 19 not more than 10 calendar days after the spill/release is discovered that includes: Operator shall immediately file a supplemental Form 19	Date: 02/28/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
All previously assigned COAs and CAs shall apply	sanchezcc	02/28/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500439	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6938410