

Inspection Photos

Loc: 380903

Operator: WAVETECH HELIUM INC

Inspection Date: 2/26/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 2. Facing northeast toward the wellsite..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:380903 | Date: 2/26/2025

Inspection Photos



Photo 2. The berm is worn down in this area. This berm is not designed to resist degradation from erosion and there are weeds growing along the berm.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:380903 | Date: 2/26/2025

Inspection Photos



Photo 3. There are undesirable weeds growing along the berm that must be controlled. The white bucket needs to be removed as well. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:380903 | Date: 2/26/2025

Inspection Photos



Photo 4. Facing toward the producing well. There are stained soils at the wellhead that must be cleaned up. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:380903 | Date: 2/26/2025

Inspection Photos



Photo 5. Facing south at the topsoil pile at the west side of the location. Topsoil is not being protected and needs to be replaced for interim reclamation.



Inspection Photos



Photo 6. View of undesirable weeds growing throughout the disturbance area. The weed debris will need to be removed and weed control will need to be performed.

