

Inspection Photos
Location: MPU Press Maint and Inject Facility
Location ID: 255968
Spill ID # 489244



Photo 1 – MPU Press Maint and Inject Facility

Photo 2 – Excavation area 1

Inspection Photos
Location: MPU Press Maint and Inject Facility
Location ID: 255968
Spill ID # 489244



Photo 3 – Excavation area and equipment

Photo 4 – Excavation area and equipment

Inspection Photos
Location: MPU Press Maint and Inject Facility
Location ID: 255968
Spill ID # 489244



Photo 5 –Excavation with impacts present

Photo 6 – Impacted soils in excavation, water was present at the time of inspection.

Inspection Photos
Location: MPU Press Maint and Inject Facility
Location ID: 255968
Spill ID # 489244



Photo 7 –Excavation area 2 next to equipment

Photo 8 – Spoil pile on liner

Inspection Photos
Location: MPU Press Maint and Inject Facility
Location ID: 255968
Spill ID # 489244



Photo 9 –Excavation area 2 at tank



Photo 10 – Impacted soils present under tank