

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2025

Submitted Date:

02/28/2025

Document Number:

710500445

**FIELD INSPECTION FORM**

Loc ID 321676 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name      | Phone          | Email                   | Comment |
|-------------------|----------------|-------------------------|---------|
| Redweik, Bob      | (281) 891-1550 | bredweik@cogc.com       | COGC    |
| Welsh, Brian      |                | brian.welsh@state.co.us |         |
| Kennedy, Herschel | 719-767-8851   | hkennedy@cogc.com       | COGC    |

**Inspected Facilities:**

| Facility ID | Type             | Status | Status Date | Well Class | API Num | Facility Name                      | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|------------------------------------|-------------|
| 480502      | TANK BATTERY     | AC     | 08/17/2021  |            | -       | Arapahoe Unit Tank Battery Sec. 28 | EI          |
| 484570      | SPILL OR RELEASE | CL     | 12/14/2023  |            | -       | Produced Water Tank                | EI          |

**General Comment:**

This is an Environmental Inspection for the Arapahoe Unit Tank Battery Sec. 28, Spill ID 484570, Rem # 32621

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |                      |       |                      |
|--------------------|----------------------|-------|----------------------|
| Yes/No             |                      |       |                      |
| Comment:           | <input type="text"/> |       |                      |
| Corrective Action: |                      | Date: | <input type="text"/> |

**Flaring:**

|                    |                      |                            |
|--------------------|----------------------|----------------------------|
| Type               |                      |                            |
| Comment:           | <input type="text"/> |                            |
| Corrective Action: |                      | Date: <input type="text"/> |

**Inspected Facilities**

Facility ID: 480502 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484570 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Waste Management:**

| Type              | Management  | Condition | GPS (Lat) | (Long) |
|-------------------|---|-----------|-----------|--------|
| Oily Soil         | Piles   |           |           |        |
| Comment           | Impacted soils were stored on location without a liner or berm.<br>Operator shall manage, store and dispose of soils in accordance with Rule 905. |           |           |        |
| Corrective Action |   |           |           | Date:  |

**Spill/Remediation:**

|                    |   |  |             |
|--------------------|---|--|-------------|
| Comment:           | At the time of inspection, for Spill ID 484570 and Rem Project # 32621. There was an open excavation at the spill location<br>Operator shall continue quarterly reporting until the site meets Table 915-1 standards. |  |             |
| Corrective Action: |   |  | Date: _____ |

|                                |  |
|--------------------------------|--|
| Emission Control Burner (ECB): | _____  |
| Comment:                       | _____  |
| Pilot: _____                   | Wildlife Protection Devices (fired vessels): _____ |

**ECMC Comments**

| Comment  | User      | Date       |
|--|-----------|------------|
| All previously assigned COAs and CAs shall apply | sanchezcc | 02/28/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 710500446    | Inspection Photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6939679">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6939679</a> |