

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1SWSE (GM 34-1 PAD)

Location ID: 334905

Date: 02/26/2025



Feb 26, 2025 at 1:42:18 PM
+39.463831, -108.058520 ±4.35m
Parachute

Photo # 5851 Entrance to location



Feb 26, 2025 at 1:53:03 PM
+39.463684, -108.058375 ±4.85m
Parachute

Photo # 5861 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1SWSE (GM 34-1 PAD)

Location ID: 334905

Date: 02/26/2025



Photo # 5852 Location



Photo # 5857 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1SWSE (GM 34-1 PAD)

Location ID: 334905

Date: 02/26/2025



Photo # 5867 NW corner of location



Photo # 5868 NE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1SWSE (GM 34-1 PAD)

Location ID: 334905

Date: 02/26/2025



Photo # 5869 SE corner of location



Photo # 5870 SW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1SWSE (GM 34-1 PAD)

Location ID: 334905

Date: 02/26/2025



Photo # 5878 Erosion in ditch/road needs maintenance/insufficient BMP's



Photo # 5879 Erosion in ditch/road needs maintenance/insufficient BMP's

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1SWSE (GM 34-1 PAD)

Location ID: 334905

Date: 02/26/2025



Photo # 5885 Open ended poly pipe/wildlife hazard NW of location on lease road



Photo # 5889 Open ended poly pipe/wildlife hazard NW of location on lease road

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1SWSE (GM 34-1 PAD)

Location ID: 334905

Date: 02/26/2025



Photo # 5894 Open ended poly pipe/wildlife hazard NW of location on lease road

