

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2025

Submitted Date:

02/26/2025

Document Number:

699506925**FIELD INSPECTION FORM**Loc ID 486772 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487189	WELL	DG	09/03/2024		001-10589	BIJOU 3-65 21-22-23 2BH	DG
487190	WELL	DG	09/01/2024		001-10590	BIJOU 3-65 21-22-23 1BH	DG
487191	WELL	DG	09/02/2024		001-10591	BIJOU 3-65 21-22-23 2AH	DG
487192	WELL	DG	08/31/2024		001-10592	BIJOU 3-65 21-22-23 1AH	DG
487193	WELL	DG	09/05/2024		001-10593	BIJOU 3-65 19-24 3BH	DG
487194	WELL	DG	08/31/2024		001-10594	BIJOU 3-65 20-19-24 2BH	DG
487195	WELL	DG	09/04/2024		001-10595	BIJOU 3-65 19-24 3AH	DG
487196	WELL	DG	08/28/2024		001-10596	BIJOU 3-65 20-19-24 1AH	DG
487197	WELL	DG	09/05/2024		001-10597	BIJOU 3-65 19-24 4AH	DG
487198	WELL	DG	08/30/2024		001-10598	BIJOU 3-65 20-19-24 2AH	DG
487199	WELL	DG	09/06/2024		001-10599	BIJOU 3-65 19-24 4BH	DG
487200	WELL	DG	08/29/2024		001-10600	BIJOU 3-65 20-19-24 1BH	DG

General Comment:

Cleanout inspection

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:			Date:		
Flaring:					
Type					
Comment:					
Corrective Action:			Date:		

Inspected Facilities

Facility ID: 487189	Type: WELL	API Number: 001-10589	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487190	Type: WELL	API Number: 001-10590	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487191	Type: WELL	API Number: 001-10591	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487192	Type: WELL	API Number: 001-10592	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487193	Type: WELL	API Number: 001-10593	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487194	Type: WELL	API Number: 001-10594	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487195	Type: WELL	API Number: 001-10595	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487196	Type: WELL	API Number: 001-10596	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487197	Type: WELL	API Number: 001-10597	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487198	Type: WELL	API Number: 001-10598	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487199	Type: WELL	API Number: 001-10599	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487200	Type: WELL	API Number: 001-10600	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Well Drilling

Rig: Rig Name: Coil Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: At time of insepction coil units were in process of cleaning out wells.

Corrective Action: _____ Date: _____

BradenHead		
Date of Last Brhd Test:	11/25/2024	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type: NONE
	End Surf Csg Pressure: 0	
Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
This inspection does not nullify any orders or corrective actions from the ECMC At time of inspection weather conditions were warm, calm, clear.	medinaj	02/26/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506926	inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6940636