

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 249-1 PAD)

Location ID: 324154

Date: 02/26/2025



Feb 26, 2025 at 3:07:23 PM
+39.464472,-108.059615 ±5.26m
Parachute

Photo # 5933 Entrance to location



Feb 26, 2025 at 3:18:36 PM
+39.464780,-108.059618 ±4.28m
Parachute

Photo # 5950 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 249-1 PAD)

Location ID: 324154

Date: 02/26/2025




Photo # 5935 Location



Photo # 5937 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 249-1 PAD)

Location ID: 324154

Date: 02/26/2025



Photo # 5956 NE corner of location



Photo # 5957 SE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 249-1 PAD)

Location ID: 324154

Date: 02/26/2025



Photo # 5958 SW corner of location



Photo # 5960 NW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 249-1 PAD)

Location ID: 324154

Date: 02/26/2025



Photo # 5944 Tank lacks required labeling/do not comply with CECMC rules



Photo # 5947 Wildlife protection for chemical containment needs maintenance/netting is damaged and open to wildlife

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NESW (GM 249-1 PAD)

Location ID: 324154

Date: 02/26/2025



Photo # 5948 Wildlife protection for chemical containment needs maintenance/netting is damaged and open to wildlife



Photo # 5955 Open ended load line