

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC EXXON-67S96W/1SESW (GM 24-1 PAD)

Location ID: 334878

Date: 02/27/2025



Photo # 6025 Entrance to location



Photo # 6044 Battery sign is weathered & illegible

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC EXXON-67S96W/1SESW (GM 24-1 PAD)

Location ID: 334878

Date: 02/27/2025



Photo # 6026 Location




Photo # 6028 Location



Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC EXXON-67S96W/1SESW (GM 24-1 PAD)

Location ID: 334878

Date: 02/27/2025



Photo # 6041 Location



Photo # 6043 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC EXXON-67S96W/1SESW (GM 24-1 PAD)

Location ID: 334878

Date: 02/27/2025



Photo # 6049 SW corner of location



Photo # 6050 NW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC EXXON-67S96W/1SESW (GM 24-1 PAD)

Location ID: 334878

Date: 02/27/2025



Photo # 6051 NE corner of location



Photo # 6052 SE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC EXXON-67S96W/1SESW (GM 24-1 PAD)

Location ID: 334878

Date: 02/27/2025



Photo # 6047 Open ended load line



Photo # 6055 Subsidence in ditch/ditch needs maintenance on SE side of location, additionally is a wildlife hazard/personnel safety hazard

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC EXXON-67S96W/1SESW (GM 24-1 PAD)

Location ID: 334878

Date: 02/27/2025



Photo # 6059 Subsidence in ditch/ditch needs maintenance on SE side of location, additionally is a wildlife hazard/personnel safety hazard



Photo # 6064 Debris

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC EXXON-67S96W/1SESW (GM 24-1 PAD)

Location ID: 334878

Date: 02/27/2025



Photo # 6066 Debris



Photo # 6068 Debris

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC EXXON-67S96W/1SESW (GM 24-1 PAD)

Location ID: 334878

Date: 02/27/2025



Photo # 6073 Unmarked deadman

