

# Inspection Photos

Loc: 321940

Operator: CITATION OIL & GAS CORP

Inspection Date: 2/26/2025

County: CHEYENNE




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321940 | Date: 2/26/2025



## Inspection Photos



**Photo 2.** Facing east at the south side of the location. This area is not reclaimed or stabilized.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321940 | Date: 2/26/2025



## Inspection Photos



**Photo 3.** There is erosion along the south side of the location and soils are not stabilized.





## Inspection Photos



**Photo 4.** There is a soil berm along the south side of the location. It is unknown if this material is being used as a berm or for reclamation. A berm must be compacted and stabilized and stormwater will still need a route to take with BMP's such as a sediment trap or rock rip/rap outlet.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321940 | Date: 2/26/2025

## Inspection Photos



**Photo 5.** The containment has woven wire for wildlife protections.





## Inspection Photos




**Photo 6.** Facing toward the tank battery.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321940 | Date: 2/26/2025

## Inspection Photos



**Photo 7.** 2024 aerial view of the location shows unused areas of the location are not reclaimed and stormwater erosion is transporting sediment offsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321940 | Date: 2/26/2025