

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location #: 418555



Photo # 9708 From entrance to location



Photo # 9709 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location #: 418555



Photo # 9710 Location



Photo # 9711 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location #: 418555




Photo # 9712 Location



Photo # 9713 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location #: 418555



Photo # 9714 Location



Photo # 9715 Location



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location #: 418555



Photo # 9716 Location



Photo # 9717 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location #: 418555



Photo # 9718 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 9719 PRV vent line does not comply with CECMC pressure safety device rules