



Hilcorp Energy Company
ALLISON UNIT 147
FORMATION FRC
LATITUDE N 37.00248
LONGITUDE W 107.56014
SE/SW, 800' FSL & 1849' FWL
SEC.24 T032N R007W
LEASE NO. FEE
API NO. 05-067-DR350
LA PLATA COUNTY, COLORADO
EMERGENCY CONTACT (505) 324-5170 OR 911
NO SMOKING NO TRESPASSING

DANGER
NO SMOKING
MATCHES OR OPEN FLAMES

Hilcorp Energy Company
PROCESSED WATER
500
BBLs

Comment: Produced water tank labels are not displaying capacity.

Corrective Action: Comply with rule 605. Install or repair sign. Date: 03/25/2025.



Comment: Leak has occurred at wellhead impacting soils around the wellhead and on the working pad surface.

Corrective Action: Comply with rule 902. clean and remediate impacted soils to 915-1 cleanup concentrations.

Additionally comply with rule 608.e. ensure mechanical integrity of well. Date: 03/25/2025



Comment: Rutting occurring at access road and active pad. Additional stabilization/grading efforts are needed to minimize degradation to the active pad.

Corrective Action: Comply with rule 1002f. Install or repair required BMPs.



