

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

06/04/2024

Document Number:

403786065

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10459 Contact Person: James Miller
Company Name: EXTRACTION OIL & GAS INC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 419648 Location Type: Production Facilities
Name: MORO FARMS NE/4 SEC 29 TANK BATTERY Number: 31-29, CNE-29
County: WELD
Qtr Qtr: NENE Section: 29 Township: 6N Range: 65W Meridian: 6
Latitude: 40.465169 Longitude: -104.681741

Description of Corrosion Protection

Extraction's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, Extraction will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. Extraction retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

Extraction's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, Extraction ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 462034 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 419400 Location Type: Well Site
Name: MORO FARMS Number: 31-29
County: WELD No Location ID
Qtr Qtr: NENE Section: 29 Township: 6N Range: 65W Meridian: 6
Latitude: 40.463580 Longitude: -104.680180

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 01/30/2011
Maximum Anticipated Operating Pressure (PSI): 1200 Testing PSI: 1300
Test Date: 08/07/2018

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 462035 Flowline Type: Wellhead Line Action Type: Out of Service

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 419400 Location Type: Well Site
Name: MORO FARMS Number: 31-29
County: WELD No Location ID
Qtr Qtr: NENE Section: 29 Township: 6N Range: 65W Meridian: 6
Latitude: 40.463580 Longitude: -104.680180

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 02/04/2011
Maximum Anticipated Operating Pressure (PSI): 1400 Testing PSI: 1000
Test Date: _____

OFF LOCATION FLOWLINE Out of Service

Date: 04/17/2024

Entire Line Removal

Partial Line Removal

Description of Out of Service:

The flowline servicing the Moro Farms 31-29 (05-123-32227) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 03/29/2022.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 462036 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 419400 Location Type: Well Site
Name: MORO FARMS Number: 31-29
County: WELD No Location ID
Qtr Qtr: NENE Section: 29 Township: 6N Range: 65W Meridian: 6
Latitude: 40.463580 Longitude: -104.680180

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 01/24/2011
Maximum Anticipated Operating Pressure (PSI): 1700 Testing PSI: 1800
Test Date: 08/07/2018

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

OPERATOR COMMENTS AND SUBMITTAL

Comments Form 44 filed to report STATUS CHANGE notification. The following flowline is now out of service: 12332227FL: services the Moro Farms 31-29 (05-123-32227)
All other flowlines will remain as previously reported.
Updated GIS data attached.
Pressure test attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 06/04/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____ Director of ECMC Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

COA Type

Description

--	--

ATTACHMENT LIST

Att Doc Num

Name

403786066	OFF-LOCATION FLOWLINE GIS SHP
403794575	PRESSURE TEST

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)