

Inspection Photos
Location: Rhoades 22-35 # 2
Location ID: 321621, Spill ID 488346
API # 05-017-06479



Photo 1 –Placard

Photo 2 – Compressor unit, evidence of cows inside guarding

Inspection Photos
Location: Rhoades 22-35 # 2
Location ID: 321621, Spill ID 488346
API # 05-017-06479



Photo 3 – Impacted soils in engine shed

Photo 4 – Impacted soils in engine shed

Inspection Photos
Location: Rhoades 22-35 # 2
Location ID: 321621, Spill ID 488346
API # 05-017-06479



Photo 5 –Equipment

Photo 6 – Impacted soils in engine shed

Inspection Photos
Location: Rhoades 22-35 # 2
Location ID: 321621, Spill ID 488346
API # 05-017-06479




Photo 7 –Wellhead and equipment