

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2025

Submitted Date:

03/03/2025

Document Number:

717701177

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site Inspection ☐
 445139 Burns, Adam 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445132	WELL	PR	09/25/2017	OW	123-42900	Cecil's Kersey Farm 17K-334	PR
445133	WELL	PR	01/01/2022	OW	123-42901	Cecil's Kersey Farm 17K-204	PR
445134	WELL	PR	11/01/2020	OW	123-42902	Cecil's Kersey Farm 17B-212	PR
445135	WELL	PR	01/01/2022	OW	123-42903	Cecil's Kersey Farm 17K-402	PR
445136	WELL	PR	09/26/2017	OW	123-42904	Cecil's Kersey Farm 17K-404	PR
445137	WELL	PR	08/01/2023	OW	123-42905	Cecil's Kersey Farm 17K-332	PR
445138	WELL	PR	08/01/2023	OW	123-42906	Cecil's Kersey Farm 17B-302	PR
445140	WELL	PR	10/01/2021	OW	123-42907	Cecil's Kersey Farm 17K-232	PR
448415	WELL	PR	08/01/2023	OW	123-43894	Cecils Kersey Farm 17B-304	PR
448416	WELL	PR	09/29/2017	OW	123-43895	Cecils Kersey Farm 17B-214	PR

General Comment:[This is a routine audit of the location](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Sound wall around the compressor and vru		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 13		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 13		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment: Air Compressor			
Corrective Action:			Date:
Type: VRU	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	300 BBLs	FIBERGLASS AST		,	
Comment: Loadout control tank						
Corrective Action:				Date:		

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition						
Other (Content)						
Other (Capacity)	23 BBLs					
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition						
Other (Content)						
Other (Capacity)	210 BBLs					
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	20	OTHER	STEEL AST		40.396870,-104.579144	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate					
Other (Content)						
Other (Capacity)	538 BBLs					
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:

Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 445132 Type: WELL API Number: 123-42900 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/17/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 445133 Type: WELL API Number: 123-42901 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/15/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 106 Fluid Type: GASEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 445134 Type: WELL API Number: 123-42902 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/17/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 445135 Type: WELL API Number: 123-42903 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHead	
Date of Last Brhd Test: 05/15/2024	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 4 Fluid Type: _____
	End Surf Csg Pressure: 0
Comment:	_____
Corrective Action:	_____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 445136	Type: WELL	API Number: 123-42904	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: PR	_____
Corrective Action:	_____ Date: _____

BradenHead	
Date of Last Brhd Test: 05/15/2024	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 5 Fluid Type: _____
	End Surf Csg Pressure: 0
Comment:	_____
Corrective Action:	_____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 445137	Type: WELL	API Number: 123-42905	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: PR	_____
Corrective Action:	_____ Date: _____

BradenHead	
Date of Last Brhd Test: 05/17/2024	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0 Fluid Type: _____
	End Surf Csg Pressure: 0
Comment:	_____
Corrective Action:	_____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 445138	Type: WELL	API Number: 123-42906	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: PR	_____
Corrective Action:	_____ Date: _____

BradenHead

Date of Last Brhd Test: 05/17/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 11 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 445140 Type: WELL API Number: 123-42907 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/15/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 448415 Type: WELL API Number: 123-43894 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/17/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 13 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 448416 Type: WELL API Number: 123-43895 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead		
Date of Last Brhd Test:	<u>05/17/2024</u>	Annual Brhd Completed? <u>Yes</u>
Last Brhd Test Results	Initial Surf Csg Pressure: <u>0</u>	Fluid Type: _____
	End Surf Csg Pressure: <u>0</u>	
Comment:	<div></div>	
Corrective Action:	<div></div>	Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717701178	Annotation Report	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6942538
717701179	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6942540