

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2025

Submitted Date:

03/03/2025

Document Number:

710500451

**FIELD INSPECTION FORM**

Loc ID 321621 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	COGC
Costa, Ryan		ryan.costa@state.co.us	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	COGC

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207544	WELL	SI	03/01/2024	OW	017-06479	RHOADES 22-35 2	EI
488346	SPILL OR RELEASE	AC	02/04/2025		-	RHOADES 22-35 #2	EI

**General Comment:**

This is an Environmental Inspection for the Rhodes 22-35 # 2 API 05-017-06479 Spill ID 488346, Rem # 38709

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	At the time of inspection fencing guarding was installed There was evidence of livestock presence within guarding area. Keep guarding secured and maintained per rule 1002			
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 207544 Type: WELL API Number: 017-06479 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 488346 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: This is an Environmental Inspection for Spill ID Spill ID 488346, Rem # 38709.

At the time of inspection impacts near the compressor were no longer visible, new gravel material was placed on the surface and a new compressor unit was installed.

In the engine building for the Pump Jack, impacted soils were visible. The Operator shall fully remediate impacted soils within the engine building. Additional sampling is needed to fully delineate impacts to soils.

The Operator shall continue quarterly reporting under Rem # 38709 until all impacted areas are compliant with Table 915-1 standards.

Operator shall manage, store and dispose of soils in accordance with Rule 905.

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500452	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6942537">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6942537</a>