

Interim Reclamation and Stormwater Inspection

Date: 02/26/2025

Operator: STRACHAN EXPLORATION INC - 83130

Location ID: 435380

Inspection Document #: 718700142

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Wickstrom 6 CTB
Location ID: 435380



Photo 1. Animal burrow observed at pit berm.

Inspection Photos
Location Name: Wickstrom 6 CTB
Location ID: 435380




Photo 2. Animal burrow observed at tank battery berm.

Inspection Photos
Location Name: Wickstrom 6 CTB
Location ID: 435380



Photo 3. Animal burrow observed at AST.



Photo 4. Stained soil and leaky valve at AST.

Inspection Photos
Location Name: Wickstrom 6 CTB
Location ID: 435380



Photo 5. Unused equipment (motor/pump) observed on south side of tank battery.

Inspection Photos
Location Name: Wickstrom 6 CTB
Location ID: 435380



Photo 6. Fitting at partially buried vessel does not appear to be properly connected.

Inspection Photos
Location Name: Wickstrom 6 CTB
Location ID: 435380



Photo 7. Southern interim areas. Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. A vegetative assessment will be performed at a later date during the active growing season to verify interim reclamation regulations and standards and will therefore remain "In-Process".

Inspection Photos
Location Name: Wickstrom 6 CTB
Location ID: 435380



Photo 8. Northeastern interim areas; see comments in Photo 7.

Inspection Photos
Location Name: Wickstrom 6 CTB
Location ID: 435380



Photo 9. Northwestern interim areas; see comments in Photo 7.