

Interim Reclamation and Stormwater Inspection

Date: 02/26/2025

Operator: STRACHAN EXPLORATION INC - 83130

Location ID: 413187

Inspection Document #: 718700143

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Chalk 31-13
Location ID: 413187




Photo 1. Stained soil observed near wellhead.

Inspection Photos
Location Name: Chalk 31-13
Location ID: 413187



Photos 2 & 3. Tank labels not adequate at day tank.




Photo 4. Unused equipment stored northwest of wellhead/pumpjack.

Inspection Photos
Location Name: Chalk 31-13
Location ID: 413187



Photo 5. Unused equipment near pumpjack unit.

Inspection Photos
Location Name: Chalk 31-13
Location ID: 413187



Photos 6 & 7. Wildlife netting at partially buried vessel and pit does not appear adequate.

Inspection Photos
Location Name: Chalk 31-13
Location ID: 413187



Photo 8. No NFPA placard at vertical heater treater.

Inspection Photos
Location Name: Chalk 31-13
Location ID: 413187



Photo 9 & 10. Stained soil and leaky valves at AST.



Photo 11. Northern interim areas, near well. Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. A vegetative assessment will be performed at a later date during the active growing season to verify interim reclamation regulations and standards and will therefore remain "In-Process".

Inspection Photos
Location Name: Chalk 31-13
Location ID: 413187



Photo 12 & 13. Western interim areas, near tank battery. See comments in Photo 11 for additional information.



Photo 14. Eastern interim areas, near pit. See comments in Photo 11 for additional information.