

Inspection Photos
Location: Craig 8-1
Location ID: 309619
API # 05-073-06320



Photo 1 –Placard at tank battery



Photo 2 – Tanks

Inspection Photos
Location: Craig 8-1
Location ID: 309619
API # 05-073-06320



Photo 3 – Impacted soils

Photo 4 – Impacted soils

Inspection Photos
Location: Craig 8-1
Location ID: 309619
API # 05-073-06320



Photo 5 –Impacted soils



Photo 6 – Impacted soils

Inspection Photos
Location: Craig 8-1
Location ID: 309619
API # 05-073-06320



Photo 7 – Impacted soils



Photo 8 – Impacted soils

Inspection Photos
Location: Craig 8-1
Location ID: 309619
API # 05-073-06320



Photo 9 – Impacted soils



**Photo 10 – Unused secondary containment,
Unmarked pipes at upper arrow**

Inspection Photos
Location: Craig 8-1
Location ID: 309619
API # 05-073-06320



Photo 11 – Stormwater issues, vehicle rutting



Photo 12 – Wellhead in fenced area

