

KT Resources LLC
Ant Hill Unit-62N97W 36NWNW
Location ID: 336462



Information missing



Stained soil

KT Resources LLC
Ant Hill Unit-62N97W 36NWNW
Location ID: 336462



Stained soil



Oily waste and staining

KT Resources LLC
Ant Hill Unit-62N97W 36NWNW
Location ID: 336462



Open end tank valve



Faded label

KT Resources LLC
Ant Hill Unit-62N97W 36NWNW
Location ID: 336462



Missing required information




Missing required information

KT Resources LLC
Ant Hill Unit-62N97W 36NWNW
Location ID: 336462



Inadequate riser protection



Gas calibration overdue

KT Resources LLC
Ant Hill Unit-62N97W 36NWNW
Location ID: 336462

Mar 3, 2025 at 10:56:26 AM

EJL 5799' Rio Blanco ROC 503

IMPACT ANALYTICAL SYSTEMS INC.
365 SOUTH MAIN
BRIGHTON, CO 80601
303-637-0150 www.impactanalytical.com

Meter S/N
15828462
C-55438

Station Name AHU 36-11 BD
Station No. 120275595 Producer 310P
Sec 36 Township 2N Range 97W
Diff 250" Temp Range 0-150 Tube Size 2067
Static 200" Absolute 11.84 psig

	Date	Orifice Plate Size	Meter Test Date	Sample Date
644	3-22-18	1.375	3-22-18	3-22-18
K8	8-22-18	1.375	8-22-18	8-22-18
K8	2-27-19	1.375	2-27-19	2-18-19
J.7941	9-11-19	1.375	9-11-19	9-11-19
	2-9-22	1.375	2-9-22	

K8



Gas calibration overdue

Washed out sediment trap

KT Resources LLC
Ant Hill Unit-62N97W 36NWNW
Location ID: 336462



Washed out check dam



Washed out check dams

**KT Resources LLC
Ant Hill Unit-62N97W 36NWNW
Location ID: 336462**



Erosion and check dam washed out



Location from Northeast corner

KT Resources LLC
Ant Hill Unit-62N97W 36NWNW
Location ID: 336462



Access road to location



Location from Southeast corner entrance