

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2025

Submitted Date:

02/25/2025

Document Number:

708303502**FIELD INSPECTION FORM**Loc ID 428684 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------------|---------|
| , TEP | | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 263532 | WELL | PR | 10/21/2002 | CBM | 045-08135 | PUCKET PA 333-34 | PR |
| 263533 | WELL | PR | 10/21/2002 | GW | 045-08136 | PUCKETT PA 43-34 | PR |
| 280291 | WELL | PR | 04/12/2006 | GW | 045-11233 | PUCKETT/TOSCO PA 543-34 | PR |
| 280292 | WELL | PR | 04/09/2006 | GW | 045-11234 | PUCKETT/TOSCO PA 643-34 | PR |
| 280294 | WELL | PR | 03/29/2006 | GW | 045-11235 | PUCKETT/TOSCO PA 443-34 | PR |

General Comment:**CECMC Inspection Report Summary**

On 2/21/2025 at approximately 11:40, Compliance Inspector Matthew Morris conducted an on-site audit at TEP ROCKY MOUNTAIN LLC, PUCKETT/TOSCO/PA 443-34 at Location ID #428684 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

- 1) Tank label is peeling and needs replaced
- 2) Stormwater; refer to Stormwater section

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Tank label is peeling and needs replaced. | | |
| Corrective Action: | Install label to comply with Rule 605.h. | Date: | 03/28/2025 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: _____

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Hog panels | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Hog panels | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Hog panels | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 6 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Horizontal Heated Separator | # 6 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 6 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 200 BBLs | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| | | | Date: | |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 263532 | Type: | WELL | API Number: | 045-08135 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 263533 | Type: | WELL | API Number: | 045-08136 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 280291 | Type: | WELL | API Number: | 045-11233 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 280292 | Type: | WELL | API Number: | 045-11234 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 280294 | Type: | WELL | API Number: | 045-11235 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|----------------------------|
| Other | Fail | | | | | Insufficient tracking BMPs |
| | | Culverts | | | | |
| Berms | | | | | | |
| Compaction | Fail | | | | | Lack of stabilization |
| | | Tracking Pad | | | | |
| | | Gravel | | | | |
| | | Compaction | | | | |
| Ditches | | | | | | |
| | | Ditches | | | | |
| Gravel | | | | | | |
| | | Check Dams | | | | |

Comment: Location surface lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/13/2025

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404106741 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6934510 |
| 708303503 | Photo Log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6934502 |