

Interim Reclamation and Stormwater Inspection

Date: 02/26/2025

Operator: RED HAWK PETROLEUM LLC - 10503

Location ID: 427144

Inspection Document #: 718700144

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Green 1-1H
Location ID: 427144



Photos 1 & 2. Northern interim areas. Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. A vegetative assessment will be performed at a later date during the active growing season to verify interim reclamation regulations and standards and will therefore remain "In-Process".

Inspection Photos
Location Name: Green 1-1H
Location ID: 427144



Photos 3 & 4. Hydrocarbon staining on equipment at wellhead and pump jack unit.

Inspection Photos
Location Name: Green 1-1H
Location ID: 427144




Photo 5. Wildlife netting inadequate at day tank.

Inspection Photos
Location Name: Green 1-1H
Location ID: 427144



Photo 6. Pump jack weights being stored on location.

Inspection Photos
Location Name: Green 1-1H
Location ID: 427144



Photos 7 & 8. Hydrocarbon staining outside of secondary containment (left; Photo 7) and within tank battery area (right; Photo 8).

Inspection Photos
Location Name: Green 1-1H
Location ID: 427144



Photos 9 & 10. Southern interim areas. Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. A vegetative assessment will be performed at a later date during the active growing season to verify interim reclamation regulations and standards and will therefore remain "In-Process".