

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2025

Submitted Date:

02/26/2025

Document Number:

715800808**FIELD INSPECTION FORM**Loc ID 318873 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242358	WELL	SI	11/01/2021	OW	123-10149	ENERGY MINERALS UNIT B 1	SI

General Comment:[This is a wellsite scout card audit followed by a field inspection.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	WEEDS	
Comment:	dead vegetation on location, around the location ROW & ancillary equip.	
Corrective Action:	Comply with rule 606	Date: 04/03/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:		
Type	PUMP JACK	
Comment:	hog fence	
Corrective Action:		Date:
Type	OTHER	
Comment:	Ancillary equip. has fabricated steel pipe and round stock	
Corrective Action:		Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	electric panel is off, meter box, transformers & telemetry		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Wednesday 2-26-2025 at approximately 1600 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc# 702403227.</p> <p>Operator: KP Kauffman</p> <p>Location name:</p> <p>Location ID # 318873</p> <p>Well Name: Energy Minerals B Unit 1</p> <p>API # 05-123-10149</p> <p>County: Weld</p> <p>Weather: Cloudy.</p> <p>Temperature: 51*</p> <p>Location: Dry.</p> <p>While there, I observed a wellsite, SI at the time of the inspection.</p> <p>During this inspection, I observed the following possible compliance issue is now delinquent:</p> <p>417.b MIT SI wells: CA Date 4-26-2024.</p> <p>606 housekeeping: CA date 4-26-2024.</p> <p>The following possible compliance issue has been addressed:</p> <p>605.g well signs have been updated.</p> <p>See attached photos.</p> <p>Due to Non-Compliance with ECMC rules, this audit/inspection will be referred to ECMC Enforcement.</p>	revasr	02/26/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404108511	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936327
715800809	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936318