

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/24/2025

Submitted Date:

02/26/2025

Document Number:

710500426

FIELD INSPECTION FORM

Loc ID 384474 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Costa, Ryan		ryan.costa@state.co.us	
Renegade		ed@renegadeoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115373	PIT				-	STATE 1	EI
212916	WELL	TA	02/06/2020	GW	061-06277	STATE 1-16	EI
384474	LOCATION	AC			-	STATE-620S52W	EI

General Comment:

This is an Environmental Inspection for the State 1-16 well location, Remediation Project # 31658

Location

Lease Road:			
Type			
comment:	Two track through pasture		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:			
Comment:	No placard onsite at the time of inspection.		
Corrective Action:		Date:	

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Flow Line	# 1			
Comment:	At the time of inspection, a flowline riser was observed at the intersection of the lease road and county road. It is not clear if the flowline infrastructure is related to the well location.			
Corrective Action:	Operator shall provide additional information for the presence or absence of flowline infrastructure at the well location.		Date:	03/26/2025

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 115373 Type: PIT API Number: - Status: _____ Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 212916 Type: WELL API Number: 061-06277 Status: TA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 384474 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Remediation Project # 31658 is ongoing. Per COAs in Form 27 Document # 403886615, ECMC removed the final closure for this Form 27, Operator shall Define the vertical and lateral extent of impacts observed in Soils Samples @, Wellhead, #4-NE Well, #5-NW Well and #6-South Well.

Additional sampling is required to fully delineate the the vertical and latera extent of impacts.

Samples shall be collected for Full Table 915-1 Contaminants of Concern.

Corrective Action: Operator shall continue Quarterly Reporting until the Site Assessment is completed and the remediation area demonstrates Compliance with Table 915-1 Standards.

Operator shall submit a Supplemental Form 27 for Remediation Project # 31658,

Date: 03/20/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 115373 Lat: 38.320150 Long: -103.242688

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: At the time of inspection there was not pit on location.

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404108498	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936271
710500427	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936264