

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404101848

Date Received:

03/05/2025

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Toews, Wesley

wtoews@blm.gov

TEP

COGCCInspectionReports@terraep.com

Haverkamp, Curtis

curtis.haverkamp@state.co.us

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708905113

Inspection Date: 11/27/2024

FIR Submit Date: 11/27/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 335136

Location Name: FEDERAL-66S94W Number: 20NENE County: \_\_\_\_\_

Qtrqtr: NENE Sec: 20 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.517053 Longitude: -107.905106

#### FACILITY - API Number: 05-045- -00 Facility ID: 335136

Facility Name: FEDERAL-66S94W Number: 20NENE

Qtrqtr: NENE Sec: 20 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.517053 Longitude: -107.905106

### CORRECTIVE ACTIONS:

1 CA# 200750

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 11/27/2024

Response: CA COMPLETED

Date of Completion: 12/04/2024

Operator Comment: Replaced 2" bradenhead ball valve coming directly off the wellhead to repair leak. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Replaced 2" bradenhead ball valve coming directly off the wellhead to repair leak. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representation

Date: 3/5/2025 9:44:51 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404101848	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files