

Inspection Photos

API: 009-06087

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 3/4/2025

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



Inspection Photos



Photo 2. The secondary containment is insufficient to contain a spill.



Inspection Photos




Photo 3. The netting on the tank is not maintained to prevent wildlife entry.

