

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2025

Submitted Date:

03/05/2025

Document Number:

717300241

FIELD INSPECTION FORM

Loc ID 327554 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247048	WELL	SI	12/01/2020	GW	123-14845	WEBBER 21-4	PA
327554	LOCATION	AC			-	WEBER-63N66W 4NENW	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 247048 Type: WELL API Number: 123-14845 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 327554 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is PA (Webber21-4); ECMC form 42 notice of start of plugging operations doc #404072325 received on 01/28/2025. The flowline servicing this well (WH/OLF) is disconnected/ isolated, valved and OOSLAT (WH & Facility). ECMC form 42 flowline pre abandonment notice doc #404075263 received 01/30/2025. No Oxy personnel on location at the time of field inspection.	maclarej	03/05/2025
As outlined on ECMC form 19 spill report Doc #404085877 received on 02/07/2025: On February 6, 2025, a release was identified due to fluid daylighting from the subsurface adjacent to the wellhead during well servicing activities at the Webber 21-4 wellhead location.	maclarej	03/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300248	PA well and signage; WH FL Isolated/ OOSLAT	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6946423
717300249	Flowline at inlet to HHS; Isolated OOSLAT	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6946424