

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/18/2025

Submitted Date:

02/27/2025

Document Number:

708700087**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Kosola, Jason 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, SIMCOE		sjninspections@ikavenergy.co	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488909	SPILL OR RELEASE	AC	01/17/2025		-	State CF1 - Dry Creek	EI

**General Comment:**

Excavation fencing is inadequate to prevent wildlife access.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					
Date: <input type="text"/>					
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	OTHER				
Comment: Pipeline excavation fencing is inadequate.					
Corrective Action: Fence pit to prevent access per rule 909.f.					
Date: 03/01/2025					
Venting:					
Yes/No					
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					
Date: <input type="text"/>					
Flaring:					
Type					
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					
Date: <input type="text"/>					

Inspected Facilities

Facility ID: 488909    Type: SPILL OR    API Number: -    Status: AC    Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404108952	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6937000">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6937000</a>
708700088	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936983">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936983</a>