

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2025

Submitted Date:

02/26/2025

Document Number:

707603695**FIELD INSPECTION FORM**Loc ID 413974 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412522	WELL	TA	10/01/2019	OW	123-30518	NORTH PLATTE 41-34	TA

General Comment:

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location IDs
(413974).

(Well(s): 2: Temporarily Abandoned | TA).

Centralized Battery Formerly served 1 Location IDs
(413457).

(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID
(Pending).

Reference (Associated Well(s), Battery Inspections):

A.) Field Inspection Report doc. #707603695 and/or Location ID #413974
for TA Well(s) info.B.) Field Inspection Report doc. #707603697 and/or Location ID #413974
for TA Well(s) info.C.) Field Inspection Report doc. #707603699 and/or Location ID #413457
for PA Well(s) info.D.) Field Inspection Report doc. #707603701 and/or Location ID #413457
for PA Well(s) info.E.) Field Inspection Report doc. #707603703 and/or Location ID #413974
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	*Refer to Emergency Contact Number section below.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Wellsite: OOSLAT applied.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: **CORRECTIVE ACTION(s) COMMENT:**
During this inspection the following possible compliance issue(s) were observed:
1.) Emergency contact number with Comapny & Well Name NOT posted at wellsite.
Refer to Rule 605.d for guidance.

Corrective Action: *Post emergency contact number with Comapny & Well Name at wellsite.
Comply with Rule 605.d. (30-days).
See photo(s) #2.
*Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.

Date: 03/31/2025

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

			CENTRALIZED BATTERY		40.363900,-104.413820	
Comment:	Centralized Battery serves 1 Location IDs (413974). (Well(s): 2: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).					
Corrective Action:					Date:	
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 412522

Type: WELL

API Number: 123-30518

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment:

Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-out, Tagged-out | LOTO.
OOSLAT at well, separator.
ECMC records last prod: 07/2018.

Form 4 on file. TA date: 08/01/2018. Approved.
DH-CIBP set.
Form 21-MIT on file. MIT date: 07/13/2020. Approved.
Form 6A on file. Out-of-Svc Designation.
Date Ceased Prod: 06/04/2019. Approved.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/16/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 12

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 02/24/2025 at approximately 14:23 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte/41-34 Pad Location ID: 413974 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>*CORRECTIVE ACTION(s) COMMENT: Refer to pg 2, Signs/Marker section.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	02/26/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404108539	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936501
707603696	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936492