

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2025

Submitted Date:

02/28/2025

Document Number:

708905854**FIELD INSPECTION FORM**Loc ID 334899 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

20 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264146	WELL	PR	11/01/2021	GW	045-08180	BENZEL 36-15B (K36B)	PR
264148	WELL	PR	06/22/2002	GW	045-08181	BENZEL 36-7C (K36B)	PR
264149	WELL	PR	04/07/2003	GW	045-08182	BENZEL 36-12A (K36B)	PR

General Comment:**CECMC Inspection/Audit Report Summary**

On 02/27/2025 at approximately 12:58 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at QB Energy BENZEL 36-15B (K36B) Pad.

Location # 334899 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Tanks & Berms - Multiple holes in liner/liner needs maintenance with a CA date of 03/20/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Any corrective actions from previous inspections/audits that have not been addressed are still applicable.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signs at separators		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Heated Separator	# 3		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	

Type: Gas Meter Run	# 3	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 3	
Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible.	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 3	
Comment:	All wells on plunger lift	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Multiple holes in liner/liner needs maintenance			
Corrective Action:	The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.			Date: 03/20/2025

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	264146	Type:	WELL	API Number:	045-08180	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	264148	Type:	WELL	API Number:	045-08181	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	264149	Type:	WELL	API Number:	045-08182	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Compaction				Light compaction in some sections
		Culverts				
		Tracking Pad				Aggregate/gravel based VTC
		Gravel				Sparse to none
Gravel						Sparse to none in areas
Ditches						
Compaction						Light compaction
Berms						

Comment: Aggregate/gravel based VTC on lease road at entrance to location - Dimensions & details are as follows - approximately 48 ft long, 18 ft wide & varying depths from 1-3 inches, length & depth insufficient, area does not appear to have been excavated & no class 2 geotextile fabric observed.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Tanks & Berms for corrective action	smelserw	02/28/2025
Any corrective actions from previous inspections/audits that have not been addressed are still applicable.		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404111871	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6939928
708905855	Inspection/Audit 708905854 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6939926
708905856	Inspection/Audit 708905854 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6939927