

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/03/2025

Submitted Date:

03/04/2025

Document Number:

715201835

FIELD INSPECTION FORM

Loc ID 321222 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 11060
Name of Operator: PROWERS ENT LLC
Address: P O BOX 7
City: LAMAR State: CO Zip: 81052

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206342	WELL	AC	07/22/1979	DM	011-06089	BROYLES C-1	AC

General Comment:

SE Compliance Specialist Brian Welsh conducted an audit and routine field inspection of the well location and equipment
This is a DM well

Location

Lease Road:

Type	Access		
comment:	Main gate is off of CR GG on the south side of the canal. Access wellhead on trail through the pasture passing by north side of old home going east to location		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Lease sign is hanging from the wellhead with minimal information		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/03/2025

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	The stock tank is rusted and hasn't been used. Tank needs to be removed		
Corrective Action:	Comply with Rule 606	Date:	04/03/2025

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Wire fence around location is in disrepair		
Corrective Action:	Comply with Rule 606	Date:	04/03/2025

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Separator on north side of wellhead. Fire tube is removed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Propane tank used as gas scrubber		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 206342 Type: WELL API Number: 011-06089 Status: AC Insp. Status: AC

Producing Well

Comment: Well is used as a DM well. Valve seems to be closed at time of inspection but inoperable and unable to open. Tubing is 2 3/8" below production master valve

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Location is covered with vegetation](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201836	location photos of wellhead, fencing and equipment	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950003