

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/03/2025

Submitted Date:

03/07/2025

Document Number:

707603731

FIELD INSPECTION FORM

Loc ID 333063 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292972	WELL	PR	06/01/2021	OW	123-26428	NOFFSINGER F 2-5	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations: Cementing; Balanced plug.
Battery: Inactive | Shut-down.
Inactive Battery SE corner GPS coordinates: 40.434786 / -104.636899
Well GPS coordinates: 40.433250 / -104.637497

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Braided wire.		
Corrective Action:		Date:	
Equipment:			
Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 292972 Type: WELL API Number: 123-26428 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Ranger Energy Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 2363' Cement Volume (sx): 10 sxs

Good Return During Job: _____ Cement Type: Class "G" Neat 15.8#

Comment: 2025/03/03:
 Plugging Operations: Cementing; Balanced plug.
 2025/03/03: JSA, digital on file.

Workover Contractor: Ranger Energy Services, Rig #BW-1543.
 Cement Contractor: Ranger Energy Services.

JSA SAFETY MEETING, CHECK PRESSURE, CP 0 PSI/SCP0 PSI TIH 2-3/8" TBG TO CIBP @ 2363' W/ 77 JNTS + 20' OF PUPS, JSA SAFETY MEETING, MIRU RES CMT, TEST PUMP LINESEST CIRC W/FW, M/W/P 10 SKS G CMT 1.15Y 2.04 BBL SLURRY 15.8 PPG, DISPLACE W/ 8.6 BBL FW TO BALANCE TOC 2234', TIIH TBG AND REVERSE OUT 30 BBL (STS) @ 1720', TOOH LD TBG, BUBBLE CHECK SURF CSG 30 MIN INFLOW TEST, JSA SAFETY MEETING AN RU RES WL, RIH W/6 SPF x 1' PERF GUN, SHOOT PERFS @ 683' (200' BELOW SCS). POOH W/ SPENT GUNS AND RDMO WL, ESTABLISH FORWARD CIRCULATION THRU PERFS @683' AND CONDITION THE HOLE 70 BBL, LET THE WELL RELAX AND BUBBLE CHECK 30 MINUTES, OBSERVED BUBBLES ON PC & SC THEN AFTER 10 MINUTES OBSERVED WATER TRICKLE ON SURF AND BUBBLES ON PROD CSG. SHUT IN FOR 1/2 HR PRESSURE BUILD AND 0 PSI BUILT, OPEN BOTH SIDES TO BUBBLE CHECKER AND OBSRVED BUBBLES ON PROD CSG ONLY, SURF CSG100% STATIC, LEAVE THE WELL OPEN FOR THE REST OF THE DAY TO RELAX, SECURE THE WELL AND LOTO, SDFN.

Corrective Action: _____ Date: _____

Workover

Comment: 2025/03/03:
 Plugging Operations: Cementing; Balanced plug.
 2025/03/03: JSA, digital on file.

Workover Contractor: Ranger Energy Services, Rig #BW-1543.
 Cement Contractor: Ranger Energy Services.

Reference:
 Form 6N on file. Notice of Intent to Abandon date: 11/06/2024. Approved.
 Form 42 on file. Notice of MIRU. Start Date: 02/25/2025. Approved.
 Form 42 on file. Notice of Plugging Operations. Start Date: 02/26/2025. Approved.
 Form 17 Brhd test on file. Date: 02/27/2025. Approved.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 03/03/2025 at approximately 12:35 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: NOFFSINGER F-65N65W/2NWNW Location ID: 333063 Well Name(s): Noffsinger F 2-5. API: 123-26428. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing; Balanced plug. Battery: Inactive Shut-down. Inactive Battery SE corner GPS coordinates: 40.434786 / -104.636899 Well GPS coordinates: 40.433250 / -104.637497</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	03/07/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603732	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950111