

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404120469

Date Received:

03/07/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

Ramsey, Scott

scott.ramsey@state.co.us

Katz, Aaron

aaron.katz@state.co.us

Haverkamp, Curtis

curtis.haverkamp@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 708905842

Inspection Date: 02/26/2025

FIR Submit Date: 02/26/2025

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 423309

Location Name: Kaufman Pad 3 Number: 11A-30-691 County: _____

Qtrqr: Lot 2 Sec: 30 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.501367 Longitude: -107.602767

FACILITY - API Number: 05-045- -00 Facility ID: 423309

Facility Name: Kaufman Pad 3 Number: 11A-30-691

Qtrqr: Lot 2 Sec: 30 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.501367 Longitude: -107.602767

CORRECTIVE ACTIONS:

2 CA# 202737

Corrective Action: Mechanical Condition - All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 02/27/2025

Response: CA COMPLETED

Date of Completion: 02/27/2025

Operator Comment: TEP field personnel responded the same day (2/26/25) that we were notified by Inspector Smelser of a potential minor leak. Field personnel had noticed bubbles in the cellar earlier in the day and had already shut the well in. A vac-truck was deployed on the following day to remove standing water from around the well head and to allow for a more thorough investigation. Field personnel determined that the bubbling was due to a leaking surface valve which was remedied on the same day. TEP will collect samples and perform the standard annual test with 7-day build up. Annual test results will be submitted to ECMC per standard procedure. This corrective action is complete.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: TEP field personnel responded the same day (2/26/25) that we were notified by Inspector Smelser of a potential minor leak. Field personnel had noticed bubbles in the cellar earlier in the day and had already shut the well in. A vac--truck was deployed on the following day to remove standing water from around the well head and to allow for a more thorough investigation. Field personnel determined that the bubbling was due to a leaking surface valve which was remedied on the same day. TEP will collect samples and perform the standard annual test with 7-day build up. Annual test results will be submitted to ECMC per standard procedure. This corrective action is complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 3/7/2025 6:18:57 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404120469	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files