

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2025

Submitted Date:

03/07/2025

Document Number:

708905919

**FIELD INSPECTION FORM**

Loc ID 335335 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256101	WELL	PR	09/20/1999	GW	045-07431	CLOUGH RMV 213-20	PR
269952	WELL	PR	03/15/2004	GW	045-09429	CLOUGH RWF 544-20	PR

**General Comment:**

[CECMC Inspection/Audit Report Summary](#)  
On 03/04/2025 at approximately 10:55 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 213-20 pad.  
Location # 335335 in Garfield County Colorado.  
Location is within High Priority/Density Habitat areas/Bald Eagle Roost site & in close proximity to NSO Habitat area.  
Location is approximately 177 yards from a creek/drainage that contributes to the Colorado River.  
Location is approximately 560 yards from the Colorado River.  
While there, I observed normal production operations.

This is a summary of inspection/audit report.

Remote location/Split pad - Wellheads only, all production equipment associated with these 2 wells is located on the CLOUGH RMV 3-20 pad location # 323886

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Plunger Lift	# 2		corrective date
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	Marked		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	No form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 256101 Type: WELL API Number: 045-07431 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 269952 Type: WELL API Number: 045-09429 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in areas
		Gravel				Sparse to none in sections
		Compaction				Light compaction in some sections
		Culverts				
Compaction						Small amount of light compaction
		Ditches				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Remote location/Split pad - Wellheads only, all production equipment associated with these 2 wells is located on the CLOUGH RMV 3-20 pad, location # 323886</a>	smelserw	03/07/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905920	Inspection/Audit 708905919 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950414">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950414</a>
708905921	Inspection/Audit 708905919 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950415">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950415</a>