

**Inspection/Audit Photos**  
**Location Name: QB Energy BENZEL 26-16 (P26NW) Pad**  
**Location ID: 335249**



**Photo # 812 From entrance to location**



**Photo # 813 From entrance to location**

# Inspection/Audit Photos

Location Name: QB Energy BENZEL 26-16 (P26NW) Pad

Location ID: 335249



Photo # 814 Location

Photo # 815 Location

**Inspection/Audit Photos**  
**Location Name: QB Energy BENZEL 26-16 (P26NW) Pad**  
**Location ID: 335249**



**Photo # 816 Location**



**Photo # 817 Location**

## Inspection/Audit Photos

Location Name: QB Energy BENZEL 26-16 (P26NW) Pad

Location ID: 335249



**Photo # 818 Location**



**Photo # 819 Flowline heating insulation cap damaged  
/available for entry by wildlife/wildlife hazard**

## Inspection/Audit Photos

Location Name: QB Energy BENZEL 26-16 (P26NW) Pad

Location ID: 335249



**Photo # 820 Flowline heating insulation damaged/available  
for entry by wildlife/wildlife hazard**