



**Inspected Facilities**

Facility ID: 209429 Type: WELL API Number: 039-06334 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/24/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
At time of inspection unable to access location due to lock on landowners gate. This inspection does not nullify any orders or corrective actions from the ECMC At time of inspection weather conditions were calm, clear, cold.	medinaj	03/05/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506977	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6951294">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6951294</a>