

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2025

Submitted Date:

03/03/2025

Document Number:

713601929

FIELD INSPECTION FORM

Loc ID 488167 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10791
Name of Operator: WAVETECH HELIUM INC
Address: 1801 BROADWAY SUITE 600
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
GENDELMAN, IGOR		igendelman@wavetechenergy.com	
Jobe, Patrick		pjobe@wavetechenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488167	LOCATION	AC			-	1 Wavetech Wulff Trust 43-	RI

General Comment:

[This is a construction inspection at the 1 Wavetech Wulff Trust #43-5 wellsite.](#)
[See attached photos and additional details within this report.](#)

Location Construction

Location ID: 488167 CDP: _____

Comment: Topsoil was salvaged and stored at the south side of the location. Contractor stated that approximately 9 inches of topsoil had been salvaged at the location.

Corrective Action: **Date:** _____

Form 2A COAs:

Comment: The Operator will submit an approved 1202.a.(3). CPW Waiver for the 1 Wavetech Wulff Trust 43-5 Location to ECMC via Form 4 Sundry not less than 30 days prior to the start of construction. It does not appear a CPW waiver was submitted via form 4 Sundry.

Corrective Action: Immediately comply with form 2A COA: 403444544. **Date:** _____

Wildlife BMPs:

Comment:

Corrective Action: **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	Yes	Vehicle Trakcing	No

Comments: Erosion BMPs: At the time of inspection only surface roughening had been performed around the location perimeter.

Other BMPs: Vehicle tracking control practices must be implemented per Rule 1002.f.(2)F.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)
Comply with Stormwater BMP's per form 2A. **Date:** 03/07/2025

5

Comment: Additional BMP's must be installed per form 2A Stormwater BMP's.

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404112472	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6941313
713601930	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6941306