

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2025

Submitted Date:

03/10/2025

Document Number:

710100352

**FIELD INSPECTION FORM**

Loc ID: 420232      Inspector Name: Anderson, Laurel      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER      State: CO      Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Noble, Legacy		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Legacy Noble Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420232	LOCATION	AC			-	MOSER H27-79HN	EI

**General Comment:**

ECMC Environmental Inspection of the following Chevron (Operator) facilities:  
[Moser PC H22-33 Tank Battery Facility ID 489488/Location ID 420232](#)

Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Current site status:**

- Peeling paint and signage/labels
- Missing tank content labels (Northernmost AST)
- Loadout piping missing camlock
- Weeds/debris/trash
- Standing water around concrete partially buried produced water vaults
- Tank contents/volume labels too small

**Location**

Overall Good:

**Signs/Marker:**

	Type	TANK LABELS/PLACARDS
	Comment:	Tank content and volume labels missing/too small to read at a distance and peeling. NFPA placards peeling.
	Corrective Action:	Install sign to comply with Rule 605.h.
		Date: 05/09/2025

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER	
	Comment:	Lack of maintenance/good housekeeping procedures. Weeds/trash/debris observed on location at the time of inspection (see photos).
	Corrective Action:	Comply with Rules 606 and 1002.f.(2).D.
		Date: 03/17/2025

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

	Type: Ancillary equipment	#		corrective date
	Comment:	Loadout connection unsecured (no cap/lock on camlock coupling) - See photos.		
	Corrective Action:			
		Date:		

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		,
	Comment:	Fiberglass 300 bbl AST (north end) no content label. Appears to be painted; paint is peeling.			
	Corrective Action:				Date:

**Paint**

Condition:

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
	Comment:			
	Corrective Action:			
		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	<100 BBLs	CONCRETE SUMP/VAULT		,	
Comment:		Two 60 bbl partially buried concrete produced water vaults. Water has pooled around both vaults.				
Corrective Action:						Date:
<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	300 BBLs	STEEL AST		,	
Comment:		Paint peeling				
Corrective Action:						Date:
<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Insufficient				
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No						
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**

Facility ID: 420232 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710100353	2025_0306_ Moser PC H22-33 Photo Documentation	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952823">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952823</a>