

Interim Reclamation and Stormwater Inspection

Date: 03/05/2025

Operator: BISON IV OPERATING LLC - 10670

Location ID: 437240

Inspection Document #: 718700169

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pronghorn K-12 Pad
Location ID: 437240



Photo 1. Sign at well does not reflect current operator of record.

Inspection Photos
Location Name: Pronghorn K-12 Pad
Location ID: 437240



Photos 2 & 3. Hydrocarbon staining observed at pumpjack unit.

Inspection Photos
Location Name: Pronghorn K-12 Pad
Location ID: 437240




Photos 4 & 5. Hydrocarbon staining observed at pumpjack unit.

Inspection Photos
Location Name: Pronghorn K-12 Pad
Location ID: 437240



Photos 6 & 7. Hydrocarbon staining observed at pumpjack unit.

Inspection Photos
Location Name: Pronghorn K-12 Pad
Location ID: 437240



Photos 8 & 9. Unused equipment and tumbleweed debris observed at well.

Inspection Photos
Location Name: Pronghorn K-12 Pad
Location ID: 437240



Photos 10 & 11. Topsoil stockpile was observed to be predominantly bare/exposed soils and requires additional reclamation activities to stabilize the stockpile from erosion degradation.

Inspection Photos
Location Name: Pronghorn K-12 Pad
Location ID: 437240



Photo 12. It appears that several cubic yards of topsoil have been removed from the stockpile.