

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2025

Submitted Date:

03/10/2025

Document Number:

710100356

FIELD INSPECTION FORM

Loc ID: 429363 Inspector Name: Anderson, Laurel On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
,		ECMCInspections@Oxy.com	All Inspections
Kiel, Macy		Macy_Kiel@oxy.com	Staff Environmental Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442606	TANK BATTERY	AC	07/23/2015		-	CANNON TANK BATTERY 16N-E3HZ	EI

General Comment:

ECMC environmental inspection to determine progress on the Cannon 36N-W3HZ Separator spill (Spill ID 489259). Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Cannon 36N-W3HZ Facility
Spill ID 489259
Tank Battery Facility ID 442606

Incident information:

Spill Discovery Date: 2/7/2025
Days since spill discovery: 31 days (as of 3/10/2025)
Last report: 19s 02/14/2025

Current site status: Separator has been disconnected and set aside to allow for remedial excavation, separator has oil and oil stained soil falling off onto ground surface below, hydrocarbon staining and odor present within the open excavation, soil appears to be comprised of silty sand/sandy silt. Water in the base of the excavation appears to be from hydrovacuuming to expose the flowlines/piping beneath the separator, orange construction fencing has fallen, gate to tank battery was open and unsecured upon arrival.

Inspected Facilities

Facility ID: 442606 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Separator has been disconnected and set aside to allow for remedial excavation, separator has oil and oil stained soil falling off onto ground surface below, hydrocarbon staining and odor present within the open excavation, soil appears to be comprised of silty sand/sandy silt.

Corrective Action: Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19 – Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director. Closure of this spill is due by January 6th, 2023.

Date: 05/08/2025

Reportable: YES _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710100357	2025_0306_ Cannon 36N-W3HZ Separator Spill_Photo Documentation	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953062