

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2025

Submitted Date:

03/11/2025

Document Number:

710100365**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Anderson, Laurel 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
,		ECMCInspections@Oxy.com	All Inspections
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483991	SPILL OR RELEASE	CL	03/10/2023		-	Warner 5-18 Flowline	EI

General Comment:

ECMC environmental inspection to determine progress on Remediation Project #26335/Spill ID #483991. Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable.
There were no operator personnel on location at the time of this field inspection.

Operator's 3rd party environmental consultant was on location at the time of this field inspection performing confirmation soil sampling. Flowline excavation was backfilled previously. ECMC witness installation of one soil boring (SB-01) to 17.5' bgs using a direct push rig. Soils appeared to be comprised of interbedded clays and sands to ~10' bgs followed by clay/silty clay to 17.5' bgs. Soil was saturated at ~8' bgs, gray staining was observed in soil recovered from between ~10-15' bgs.
Photos attached to document site conditions.

Incident information:Spill Discovery Date: 3/10/2023Days since spill discovery: 732 daysLast report: Form 27s Doc #403954911 was received on 10/17/2024As of 3/11/2025 Operator is 55 days late on quarterly reporting (90 days).

Inspected Facilities									
Facility ID:	483991	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental		
Spill/Remediation:		
Comment:	Quarterly reporting is required for Remediation Project #26335 Last report: Form 27s Doc #403954911 was received on 10/17/2024 As of 3/11/2025 Operator is 55 days late on quarterly reporting (90 days).	
Corrective Action:	In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (every 90 days). CA due date back dated to when last Supplemental Form 27 was due.	Date: 01/15/2025
Emission Control Burner (ECB): _____		
Comment: _____		
Pilot: _____ Wildlife Protection Devices (fired vessels): _____		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710100366	2025_0306_ Warner 5-18_Photo Documentation	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953804