

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2025

Submitted Date:

03/11/2025

Document Number:

698603206

**FIELD INSPECTION FORM**

Loc ID 304782 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274917	WELL	PR	04/12/2005	GW	125-08980	MCCONNELL 4-6	PR

**General Comment:**

Routine Inspection.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Active agricultural cropland with seasonal access to well location.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign at wellhead location.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign posted at remote Gas Meter Run.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact information posted on Lease sign.		Date: _____
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Open ended black poly line at wellhead.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Dehydrator	# 1		corrective date
Comment:	Dehydrator (Drip Bottle) on gas meter run inlet.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing removed from the wellbore. Casing valve open.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:	Remote Gas Meter Run located on CR 53 & CR Q at shared gathering location. Digital Gas Meter Run. Meter Calibration/Test Log dated 3-13-23. Well Inlet Valve open. Gas Outlet Valve open. Meter not calibrated annually.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	04/11/2025
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Remote Gas Meter Shed.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 274917 Type: WELL API Number: 125-08980 Status: PR Insp. Status: PR

**Producing Well**

Comment: Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.  
Electronic Well File reflects last Production/Status reported 1/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603222	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6954319">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6954319</a>