

**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Missing information**



**Unused equipment**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Damaged label**



**Oily waste. Staining**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Staining**



**Staining**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Unused equipment**



**Unused equipment**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Staining**



**Unused equipment**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Unlabeled and nused equipment**



**Unused equipment**





**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Storage yard**



**Open to wildlife and personnel**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Open to wildlife and personnel**



**Debris. Unprotected flowline.**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Oily waste**



**Missing information**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Leaking equipment**



**Staining**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Debris**



**Unused equipment**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Unprotected relief riser**



**Open to wildlife**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**




**Open to wildlife and personnel**



**Open to wildlife and personnel**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Unprotected vent riser**



**Oily waste. Open to wildlife.**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Debris storage**



**Debris storage**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Unused and unlabeled equipment**




**Tank battery.**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Oily waste and staining**



**Unlabeled tank**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Debris**



**Oily waste and staining**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Open end tank valve**




**Damaged label**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Oily waste and staining**



**Unlabeled tank**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Unused equipment**



**Oily waste. Open to wildlife.**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Open pit**



**Open pit**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Tank battery**



**Oily waste. Staining.**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Location from East corner**



**Location from North corner**



**Antler Energy LLC  
USA-Clark – Millison 1  
Location ID: 313122**



**Location from West corner**



**Location from South corner**