

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Information missing



Oily waste and contaminated soil.

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Oily waste and stained soil.

Oily waste and stained soil.

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Debris. Oily waste and stained soil.




Oily waste

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Debris



Oily waste and staining

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Staining



Debris. Stained soil.

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Missing required information



No sign at tank battery

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Staining



Leaking open end load line

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Debris



Production pit on location

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Production pit on location



Production pit on location

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Oily waste and staining



Oily waste and staining

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Debris



Location from Northeast entrance

**Antler Energy LLC
Ptasynski 1X
Location ID: 313300**



Location from Northwest corner



Location from Southwest corner